

Report No.: FA232203


Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUNEO Page Number : D1 of D2
Report Issued Date : Apr. 26, 2012
Report Version : Rev. 01









TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUNEO Page Number : D2 of D2
Report Issued Date : Apr. 26, 2012
Report Version : Rev. 01

Report No.: FA232203



Report No.: FA232203

Appendix E. Test Setup Photos



Right Cheek


Right Tilted








Left Tilted



Face of the DUT with Phantom 1.5 cm Gap (DUT with Earphone)



Bottom of the DUT with Phantom 1.5 cm Gap (DUT with Earphone)

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUNEO Page Number : E1 of E2
Report Issued Date : Apr. 26, 2012
Report Version : Rev. 01










Report No. : FA232203

Right Cheek

Left Cheek



Bottom of the DUT with Phantom 1.5 cm Gap (DUT with Earphone)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUNEO

Page Number : E2 of E2 Report Issued Date: Apr. 26, 2012 Report Version : Rev. 01