

Report No.: FA331305

Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDIVA Page Number : D1 of D2
Report Issued Date : Mar. 26, 2013
Report Version : Rev. 01



Antenna Location :



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDIVA Page Number : D2 of D2
Report Issued Date : Mar. 26, 2013
Report Version : Rev. 01

Report No.: FA331305



Report No.: FA331305

Appendix E. Test Setup Photos



Right Cheek

Right Tilted







Left Tilted



Front of the DUT with Phantom 1.5 cm Gap



Back of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDIVA Page Number : E1 of E1
Report Issued Date : Mar. 26, 2013
Report Version : Rev. 01