


Report No.: FA1D0807


## Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSWING Page Number : D1 of D2
Report Issued Date : Dec. 15, 2011
Report Version : Rev. 01









TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSWING Page Number : D2 of D2
Report Issued Date : Dec. 15, 2011
Report Version : Rev. 01



## Report No.: FA1D0807


## Appendix E. Test Setup Photos



Right Cheek - Slide up



Right Tilted - Slide up



Left Cheek - Slide up



Left Tilted - Slide up

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSWING Page Number : E1 of E1
Report Issued Date : Dec. 15, 2011

Report Version : Rev. 01







**Right Cheek - Slide Down** 



Report No.: FA1D0807

**Right Tilted - Slide Down** 



Left Cheek - Slide Down



Left Tilted - Slide Down



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSWING

Page Number : E2 of E2 Report Issued Date: Dec. 15, 2011 Report Version : Rev. 01