

Report No.: FA0O2916B

Appendix D. Product Photos






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPEED Page Number : D1 of D2
Report Issued Date : Nov. 15, 2010
Report Version : Rev. 01



FCC SAR Test Report

Antenna Location:



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPEED Page Number : D2 of D2
Report Issued Date : Nov. 15, 2010
Report Version : Rev. 01

Report No.: FA0O2916B



Report No.: FA0O2916B

Appendix E. Test Setup Photos



Right Cheek

Right Tilted







Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPEED Page Number : E1 of E1
Report Issued Date : Nov. 15, 2010
Report Version : Rev. 01