



Report No. : FA380112

Appendix D. **Test Setup Photos**



Right Cheek




Left Cheek **Left Tilted**

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEONE Page Number : D1 of D2 Report Issued Date: Aug. 20, 2013 : Rev. 01 Report Version









Report No. : FA380112

Back of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEONE Page Number : D2 of D2
Report Issued Date : Aug. 20, 2013
Report Version : Rev. 01