


Report No.: FA130433B

Appendix D. Product Photos








SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC Page Number : D1 of D2
Report Issued Date : Apr. 26, 2011
Report Version : Rev. 02



Antenna Location:



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC Page Number : D2 of D2 Report Issued Date : Apr. 26, 2011 Report Version : Rev. 02

Report No. : FA130433B



Report No.: FA130433B

Appendix E. **Test Setup Photos**



Right Cheek









Left Tilted



Front Face of the DUT with Phantom 1 cm Gap (DUT without Earphone)



Rear Face of the DUT with Phantom 1 cm Gap (DUT without Earphone)

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC

Page Number : E1 of E2 Report Issued Date: Apr. 26, 2011 Report Version : Rev. 02







Rear Face of the DUT with Phantom 1 cm Gap (DUT with Earphone)



Report No.: FA130433B

Right Side of the DUT with Phantom 1 cm Gap (DUT without Earphone)



Bottom Side of the DUT with Phantom 1 cm Gap (DUT without Earphone)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC

Page Number : E2 of E2 Report Issued Date: Apr. 26, 2011 Report Version : Rev. 02