

Report No.: FA231606

Appendix D. Product Photos





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH Page Number : D1 of D1
Report Issued Date : Apr. 06, 2012
Report Version : Rev. 01



Report No.: FA231606

Appendix E. Test Setup Photos





Right Cheek








Left Cheek

Left Tilted









Front of DUT with Earphone to Phantom 1 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH Page Number : E1 of E2
Report Issued Date : Apr. 06, 2012
Report Version : Rev. 01



Back of DUT with Phantom 1 cm Gap



Report No.: FA231606

Back of DUT with Earphone to Phantom 1 cm Gap



Left Side of DUT with Phantom 1 cm Gap



Right Side of DUT with Phantom 1 cm Gap



Top Side of DUT with Phantom 1 cm Gap



Bottom Side of DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH Page Number : E2 of E2
Report Issued Date : Apr. 06, 2012

Report Version : Rev. 01