


Report No. : FA1D1601

Appendix D. Product Photos








TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLURAVE Page Number : D1 of D1
Report Issued Date : Jan. 13, 2012
Report Version : Rev. 01



Report No.: FA1D1601


Appendix E. Test Setup Photos





Right Cheek







SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLURAVE

Page Number : E1 of E2 Report Issued Date: Jan. 13, 2012

Report Version : Rev. 01



Front of the DUT with Phantom 1 cm Gap



Report No. : FA1D1601

Bottom Side of the DUT with Phantom 1 cm Gap



Back of the DUT with Phantom 1 cm Gap



Back with Earphone of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLURAVE Page Number : E2 of E2
Report Issued Date : Jan. 13, 2012
Report Version : Rev. 01