

Report No.: FD090827


Appendix B. Setup Photographs

<Conducted Emission>

Mode 5



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBMN Page Number : B1 of B4 Report Issued Date : Sep. 28, 2010 Report Version : Rev. 01





Report No.: FD090827



Side View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBMN Page Number : B2 of B4
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01






<Radiated Emission>

Mode 4



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBMN Page Number : B3 of B4
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01

Report No.: FD090827





Report No.: FD090827



Remote View

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBMN Page Number : B4 of B4
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01