

# Appendix B. Setup Photographs

# <Conducted Emission>

## Mode 1



#### Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : B1 of B3
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01

**Report No. : FC330701** 



# <Radiated Emission>

## Mode 1

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : B2 of B3
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01


**Report No. : FC330701** 






Mode 4

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : B3 of B3
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01

**Report No. : FC330701**