



Report No.: FR061724

Appendix B. Setup Photographs

<Conducted Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 Page Number : B1 of B4 Report Issued Date: Aug. 06, 2010

Report Version : Rev. 01





Report No.: FR061724




Side View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 Page Number : B2 of B4
Report Issued Date : Aug. 06, 2010
Report Version : Rev. 01



<Radiated Emission>



Front View



Rear View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 Page Number : B3 of B4
Report Issued Date : Aug. 06, 2010
Report Version : Rev. 01

Report No.: FR061724



Report No.: FR061724



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 Page Number : B4 of B4
Report Issued Date : Aug. 06, 2010
Report Version : Rev. 01