


page 1 of 3

## ANNEX C INTERNAL PHOTOS



150254\_10.JPG: TNLR-Q80L400-H1147, PCB, top view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F150254E1

 Date of issue:
 22 June 2015
 Order No.:
 15-110254



## ANNEX C INTERNAL PHOTOS




150254\_11.JPG: TNLR-Q80L400-H1147, PCB, bottom view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F150254E1

 Date of issue:
 22 June 2015
 Order No.:
 15-110254



## ANNEX C INTERNAL PHOTOS



150254\_12.JPG: TNLR-Q80L400-H1147, PCB, bottom view, shielding removed

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F150254E1

 Date of issue:
 22 June 2015
 Order No.:
 15-110254

 page 3 of 3
 15-110254
 15-110254