




153143\_a.JPG: TN902-Q175L200-H1147, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 15-113143

 page 1 of 8






153143\_c.JPG: TN902-Q175L200-H1147, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 F153143E1

 15-113143
 page 2 of 8





153143\_b.JPG: TN902-Q175L200-H1147, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 F153143E1

 15-113143
 page 3 of 8





153143\_d.JPG: TN902-Q175L200-H1147, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 15-113143

 page 4 of 8





153143\_e.JPG: TN902-Q175L200-H1147, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 F553143E1

 15-113143
 page 5 of 8






153143\_i.JPG: TN902-Q175L200-H1147, test set-up open area test site

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 15-113143

 page 6 of 8





153143\_k.JPG: TN902-Q175L200-H1147, test set-up conducted measurements

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 15-113143

 page 7 of 8





153143\_j.JPG: TN902-Q175L200-H1147, test set-up shielded room

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 F153143E1

 15-113143
 page 8 of 8