




153142\_a.JPG: TN902-Q120L130H1147, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153142E1, 2<sup>nd</sup> version

 Date of issue:
 11/17/2015
 Order Number:
 15-113142
 page 1 of 8





153142\_b.JPG: TN902-Q120L130H1147, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153142E1, 2<sup>nd</sup> version

 Date of issue:
 11/17/2015
 Order Number:
 15-113142
 page 2 of 8






153142\_e.JPG: TN902-Q120L130H1147, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153142E1, 2<sup>nd</sup> version

 Date of issue:
 11/17/2015
 Order Number:
 15-113142
 page 3 of 8





153142\_c.JPG: TN902-Q120L130H1147, test set-up fully anechoic chamber

Test engineer: Thomas KÜHN Report Number: F153142E1, 2<sup>nd</sup> version Date of issue: 11/17/2015 Order Number: 15-113142



page 5 of 8

### Annex A: Test setup photographs



153142\_d.JPG: TN902-Q120L130H1147, test set-up fully anechoic chamber

Test engineer: Thomas KÜHN Report Number: F153142E1, 2<sup>nd</sup> version
Date of issue: 11/17/2015 Order Number: 15-113142






153142\_g.JPG: TN902-Q120L130H1147, test set-up open area test site

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153142E1, 2<sup>nd</sup> version

 Date of issue:
 11/17/2015
 Order Number:
 15-113142
 page 6 of 8





153142\_i.JPG: TN902-Q120L130H1147, test set-up conducted measurements

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153142E1, 2<sup>nd</sup> version

 Date of issue:
 11/17/2015
 Order Number:
 15-113142
 page 7 of 8





153142\_h.JPG: TN902-Q120L130H1147, test set-up shielded room

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153142E1, 2<sup>nd</sup> version

 Date of issue:
 11/17/2015
 Order Number:
 15-113142
 page 8 of 8