Test report No. : 10279739H-C-R2
Page : 84 of 86
Issued date : August 18, 2014
Revised date : September 4, 2014
FCC ID : YR7AERODRP5

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10279739H-C-R2
Page : 85 of 86
Issued date : August 18, 2014
Revised date : September 4, 2014
FCC ID : YR7AERODRP5

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10279739H-C-R2
Page : 86 of 86
Issued date : August 18, 2014
Revised date : September 4, 2014
FCC ID : YR7AERODRP5

Worst Case Position


Above 1GHz: Main Antenna

(Horizontal: Y-axis/ Vertical:X-axis)

Above 1GHz: Sub Antenna

(Horizontal: Y-axis/ Vertical: Y-axis) Below 1GHz: Main & Sub Antenna

(Horizontal: Z-axis_With Cradle / Vertical: Z-axis_With Cradle)









End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124