Test report No. : 10279739H-A-R1
Page : 49 of 51
Issued date : August 18, 2014
Revised date : September 2, 2014
FCC ID : YR7AERODRP5

# **APPENDIX 3: Photographs of test setup**

# **Conducted Emission**




Photo 1




Photo 2

### UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10279739H-A-R1
Page : 50 of 51
Issued date : August 18, 2014
Revised date : September 2, 2014
FCC ID : YR7AERODRP5

# **Radiated Spurious Emission**



Photo 1




Photo 2

# UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10279739H-A-R1
Page : 51 of 51
Issued date : August 18, 2014
Revised date : September 2, 2014
FCC ID : YR7AERODRP5

### **Worst Case Position**


Above 1GHz: Main Antenna

(Horizontal: Y-axis/ Vertical: X-axis)

**Above 1GHz: Sub Antenna** 

(Horizontal: Y-axis/ Vertical: Y-axis) Below 1GHz: Main & Sub Antenna

(Horizontal: Z-axis\_With Cradle / Vertical: Z-axis\_With Cradle)









**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124