
Test report No.: 31HE0102-SH-04-A


Page : 77 of 78

Issued date : December 2, 2011 FCC ID : YR7AERODRP2

APPENDIX 3: Photographs of test setup

Spurious Emission (Radiated emission)







UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No.: 31HE0102-SH-04-A


Page : 78 of 78

Issued date : December 2, 2011 FCC ID : YR7AERODRP2

Pre-check of the worst position







UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401