
Test report No. : 11834855S-C-R3
Page : 179 of 181
Issued date : March 5, 2018
FCC ID : YSKW80

APPENDIX 3: Photographs of test setup

Conducted Emission






UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 11834855S-C-R3
Page : 180 of 181
Issued date : March 5, 2018
FCC ID : YSKW80

Radiated Spurious Emission







UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


Test report No. : 11834855S-C-R3
Page : 181 of 181
Issued date : March 5, 2018
FCC ID : YSKW80

Worst Case Position


X-axis



Y-axis



Z-axis



End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401