
Test report No.: 10004229S-A-R1 Page : 66 of 68

APPENDIX 3: Photographs of test setup

Conducted emission








UL Japan, Inc. **Shonan EMC Lab.**


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile +81 463 50 6401

Test report No. : 10004229S-A-R1 Page : 67 of 68

Radiated emission







UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test report No.: 10004229S-A-R1 Page: 68 of 68

Pre-check of the worst position: Module & Antenna







END OF REPORT

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401