
Test report No. : 11834855S-B-R1
Page : 52 of 54
Issued date : March 1, 2018
FCC ID : YSKW80

## **APPENDIX 3: Photographs of test setup**

## **Conducted Emission**





### UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 11834855S-B-R1
Page : 53 of 54
Issued date : March 1, 2018
FCC ID : YSKW80


# **Radiated Spurious Emission**


### Below 1 GHz





#### Above 1 GHz





1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

 Test report No.
 : 11834855S-B-R1

 Page
 : 54 of 54

 Issued date
 : March 1, 2018


 FCC ID
 : YSKW80

# **Worst Case Position**


X-axis



Y-axis



**Z**-axis



**End of Report** 

## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401