




181631\_247\_BTLE\_01.JPG: Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F181631E3

 Date of issue:
 28.02.2019
 Order Number:
 18-111631

Page 1 of 7





181631\_247\_BTLE\_03.JPG: Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F181631E3

 Date of issue:
 28.02.2019
 Order Number:
 18-111631

 page 2 of 7
 7






181631\_247\_BTLE\_04.JPG: Test setup – radiated test on open area test site

 Examiner:
 Paul NEUFELD
 Report Number:
 F181631E3

 Date of issue:
 28.02.2019
 Order Number:
 18-111631

 page 3 of 7





181631\_247\_BTLE\_05.JPG: Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F181631E3

 Date of issue:
 28.02.2019
 Order Number:
 18-111631

Page 4 of 7






181631\_247\_BTLE\_06.JPG: Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F181631E3

 Date of issue:
 28.02.2019
 Order Number:
 18-111631

Page 5 of 7





181631\_247\_BTLE\_07.JPG: Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F181631E3

 Date of issue:
 28.02.2019
 Order Number:
 18-111631





181631\_247\_BTLE\_08: Test setup – conducted emissions on power supply lines

 Examiner:
 Paul NEUFELD
 Report Number:
 F181631E3

 Date of issue:
 28.02.2019
 Order Number:
 18-111631