


Annex A




101523mag1.JPG

 Testengineer:
 Michael DINTER
 Report Number:
 F101523E2

 Date of issue:
 07 October 2010
 Order Number:
 101523
 page 1 of 6






101523emi1.JPG

 Testengineer:
 Michael DINTER
 Report Number:
 F101523E2

 Date of issue:
 07 October 2010
 Order Number:
 101523
 page 2 of 6





101523emiff1.JPG

 Testengineer:
 Michael DINTER
 Report Number:
 F101523E2

 Date of issue:
 07 October 2010
 Order Number:
 101523
 page 3 of 6





101523magff1.JPG

 Testengineer:
 Michael DINTER
 Report Number:
 F101523E2

 Date of issue:
 07 October 2010
 Order Number:
 101523
 page 4 of 6





101523magff2.JPG

 Testengineer:
 Michael DINTER
 Report Number:
 F101523E2

 Date of issue:
 07 October 2010
 Order Number:
 101523
 page 5 of 6





101523clima1.JPG

 Testengineer:
 Michael DINTER
 Report Number:
 F101523E2

 Date of issue:
 07 October 2010
 Order Number:
 101523
 page 6 of 6