
: 12407798S-A-R2 Test report No. : 45 of 47 Page : April 1, 2019 : YUQ-W510MV **Issued date** FCC ID

APPENDIX 3: Photographs of test setup

Conducted Emission

Front







UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


 Test report No.
 : 12407798S-A-R2


 Page
 : 46 of 47

 Issued date
 : April 1, 2019

 FCC ID
 : YUQ-W510MV

Radiated Spurious Emission







UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


 Test report No.
 : 12407798S-A-R2

 Page
 : 47 of 47


 Issued date
 : April 1, 2019

 FCC ID
 : YUQ-W510MV

Worst Case Position







End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401