Test report No.
 : 11825847S-A-R2


 Page
 : 34 of 36

 Issued date
 : January 26, 2018

 FCC ID
 : YUQ-W410MV

### **APPENDIX 3: Photographs of test setup**

# **Conducted Emission**





#### UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


 Test report No.
 : 11825847S-A-R2


 Page
 : 35 of 36

 Issued date
 : January 26, 2018


 FCC ID
 : YUQ-W410MV


## **Radiated Spurious Emission**





Below 1 GHz





Above 1 GHz

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

 Test report No.
 : 11825847S-A-R2

 Page
 : 36 of 36

 Issued date
 : January 26, 2018

 FCC ID
 : YUQ-W410MV

## **Worst Case Position**







**End of Report** 

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401