


Inside view of EUT #1



Report no. ETLE110610.0504, Page D1 of D16



Inside view of EUT #2



Report no. ETLE110610.0504, Page D2 of D16




Inside view of EUT #3



Report no. ETLE110610.0504, Page D3 of D16




Top side view of main board



Report no. ETLE110610.0504, Page D4 of D16



Bottom side view of main board



Report no. ETLE110610.0504, Page D5 of D16




Top side view of sub board 1



Report no. ETLE110610.0504, Page D6 of D16




Bottom side view of sub board 1



Report no. ETLE110610.0504, Page D7 of D16




Top side view of sub board 2



Report no. ETLE110610.0504, Page D8 of D16




Bottom side view of sub board 2



Report no. ETLE110610.0504, Page D9 of D16




Top side view of connector board



Report no. ETLE110610.0504, Page D10 of D16




Bottom side view of connector board



Report no. ETLE110610.0504, Page D11 of D16




Top side view of sensor board



Report no. ETLE110610.0504, Page D12 of D16




Bottom side view of sensor board



Report no. ETLE110610.0504, Page D13 of D16



Top side view of scanner board



Report no. ETLE110610.0504, Page D14 of D16



Bottom side view of scanner board



Report no. ETLE110610.0504, Page D15 of D16



Front view of motor



Rear view of motor



Report no. ETLE110610.0504, Page D16 of D16