


Inside view of EUT #1



Report no. ETLE110715.0618, Page D1 of D12




Inside view of EUT #2



Report no. ETLE110715.0618, Page D2 of D12




Inside view of EUT #3



Report no. ETLE110715.0618, Page D3 of D12




Top side view of main board



Report no. ETLE110715.0618, Page D4 of D12




Bottom side view of main board



Report no. ETLE110715.0618, Page D5 of D12




Top side view of sub board



Report no. ETLE110715.0618, Page D6 of D12




Bottom side view of sub board



Report no. ETLE110715.0618, Page D7 of D12




Top side view of sensor board



Report no. ETLE110715.0618, Page D8 of D12



Bottom side view of sensor board



Report no. ETLE110715.0618, Page D9 of D12



Top side view of scanner board



Report no. ETLE110715.0618, Page D10 of D12



Bottom side view of scanner board



Report no. ETLE110715.0618, Page D11 of D12



View of motor

