


Appendix D. Product Photos




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-TSI12 Page Number : D1 of D2
Report Issued Date : Jun. 27, 2011
Report Version : Rev. 01

Report No.: FA151009A



Report No.: FA151009A

Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID:

Page Number : D2 of D2
Report Issued Date : Jun. 27, 2011
Report Version : Rev. 01



est Report No. : FA151009A

Appendix E. Test Setup Photos





Right Cheek











Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-TSI12 Page Number : E1 of E1
Report Issued Date : Jun. 27, 2011
Report Version : Rev. 01