


Report No.: FA342939


## Appendix D. SAR Test Setup Photos









**Right Tilted** 



Left Cheek



**Left Tilted** 



Right Cheek with battery2



Left Cheek with battery2

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YY3-NX1UMTS Page Number : D1 of D4 Report Issued Date: Jan. 14, 2014 Report Version : Rev. 01



## FCC SAR Test Report



Left Tilted with battery2

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YY3-NX1UMTS Page Number : D2 of D4 Report Issued Date: Jan. 14, 2014


Report No. : FA342939

Report Version : Rev. 01






Back, Test Separation 1.5 cm




Report No.: FA342939


Back, Test Separation 1 cm




Back with battery2, Test Separation 1 cm



Front, Test Separation 1.5 cm



Front, Test Separation 1 cm




Left Side, Test Separation 1 cm

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YY3-NX1UMTS Page Number : D3 of D4
Report Issued Date : Jan. 14, 2014
Report Version : Rev. 01





Right Side, Test Separation 1 cm

Top Side, Test Separation 1 cm



**Bottom, Test Separation 1 cm** 

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YY3-NX1UMTS Page Number : D4 of D4 Report Issued Date: Jan. 14, 2014

Report Version : Rev. 01