Dear Timco,

Responses in Blue

PREVIOUS ISSUES:

1. 731 FORM: Please correct the customer information listed on item 5 of the 731 form. The correct customer should be "GLOBAL EMC" Thank you.

Corrected – See revised upload

2. AUTHORIZATION LETTER: Please send an authorization letter that states "Adrian Hartog" can sign the documents. Thank you.

See authorization letter upload. Note that Adrian Hartog is the CEO of mySpark, and is granting Ernest Yeung the authority to sign documents.

NEW ISSUES:

- 3. 731 FORM:
 - a. Item 4: All of the documentation for the filing has the FCC ID: Z4J-2001101-001A. Please correct the Equipment Product Code: -2001101-001A
 - b. Item 10: Please correct the Equipment Class: DSS
 - c. Item 13: Please add the FCC Rule Part: 15.247

Corrected – See revised upload

4. LABEL: As per Part 15.19, please include the following on the label:

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Note: This issue was discussed with Timco and no revision is being submitted at this point in time. For reference, the client has attested that similar devices do not have the same statement and requests equal treatment towards this portion of their certification.

1. TEST REPORT:

a. Pages 67-69: The graphs have an asterisk "*" in the top right corner. Please note that the accuracy of such traces is questionable and should not be used for certification purposes. Please explain or revise.

For clarity, these graphs have been re-measured. However, since these were max hold plots and the trace was evidently completed, we hypothesize that the sequence of buttons pressed prior to capturing the plots was incorrect.