## Hunan Novasky Electronic Technology Co., Ltd.

Office Building, Wanxuyuan, No. 203 Sanyi Avennue, Changsha, Hunan, China Tel: 86-731-82369888 Fax: 86-731-82369892

## To Whom it May Concern

Applicant: Hunan Novasky Electronic Technology Co., Ltd.

FCC ID: ZIXDN-XXX

Pursuant to the requirements contained in Part 15.121 of the Commission's Rules, this scanning receiver does not have the capability of tuning the frequencies assigned to the Domestic Public Cellular Radio Telecommunications Service.

In this circuitry, this device is not readily alterable to restore the cellular band coverage because the inventory of frequencies contained within this band is not available in the microprocessor.

Also, the microprocessor is fixed soldered and not easily removable. In addition, the critical circuitry is "hardened" with a black epoxy that covers the area of the circuitry that might be modified to circumvent the design efforts referenced above.

Therefore, since the clipping of leads; or the installation of a simple component such as a diode, resistor, or a jumper wire; or the reprogramming of any semiconductor device contained within this unit cannot be accomplished using a special access code or a personal computer; This is to certify that the conditions mandated in part 15.121 have been met.

Corr Lee, Stock Commisioner