There is no tune-up facility for the radio module. All settings are made at the factory.