## FCC Test Report

# **Appendix A. Test Photos**

Report No.: FR452053AD

SPORTON INTERNATIONAL INC. Page No. : A1 of A6 TEL: 886-3-327-3456 Report Version : Rev. 01





Report No.: FR452053AD

## 1 Photographs of Conducted Emissions Test Configuration



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01






**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




### 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 




**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A4 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



#### For radiated emissions 30MHz~1GHz



#### **FRONT VIEW**



#### **REAR VIEW**


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6

Report Version : Rev. 01



#### For radiated emissions above 1GHz



**FRONT VIEW** 



#### **REAR VIEW**

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01