

Appendix A. Test Photos

Report No.: FR452053AN

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No.: FR452053AN

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



Page No.

Report Version

: A2 of A6

: Rev. 01

REAR VIEW

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456



FCC Test Report No.: FR452053AN



SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report No.: FR452053AN

2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A4 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report

Report No.: FR452053AN

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A5 of A6 : Rev. 01


Report Version



FCC Test Report

Report No.: FR452053AN

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01