

**Appendix A. Test Photos** 

Report No.: FR422631TO

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report No.: FR422631TO

## 1 Photographs of Conducted Emissions Test Configuration



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report No.: FR422631TO



**SIDE VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report No.: FR422631TO

## 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A4 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report

Report No. : FR422631TO

For radiated emissions 30MHz~1GHz

Mode 1



## **FRONT VIEW**



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6


Report Version : Rev. 01



FCC Test Report


For radiated emissions above 1GHz

Mode 2



Report No.: FR422631TO

**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A6 Report Version : Rev. 01