



153494_I_U_A.JPG: ZONESCAN 820 Logger with integrated antenna, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494
 page 1 of 16





153494_I_U_B.JPG: ZONESCAN 820 Logger with integrated antenna, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494
 page 2 of 16





153494_I_U_G.JPG: ZONESCAN 820 Logger with integrated antenna, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 F153494E3

 15-113494
 page 3 of 16





153494_I_U_I.JPG: ZONESCAN 820 Logger with integrated antenna, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494

 page 4 of 16






153494_I_U_J.JPG: ZONESCAN 820 Logger with integrated antenna, test setup fully open area test site

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494

 page 5 of 16






153494_X_U_A.JPG: ZONESCAN 820 Logger with integrated antenna, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494

 page 6 of 16
 page 6 of 16






153494_X_U_G.JPG: ZONESCAN 820 Logger with integrated antenna, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494

 page 7 of 16





153494_X_U_L.JPG: ZONESCAN 820 Logger with external antenna, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494

 page 8 of 16





153494_X_U_P.JPG: ZONESCAN 820 Logger with external antenna, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494

 page 9 of 16






153494_X_U_H.JPG: ZONESCAN 820 Logger with external antenna, test setup fully open area test site

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494

 page 10 of 16






153494_X_U_R.JPG: ZONESCAN 820 Logger with external antenna, test setup conducted measurements

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494

 page 11 of 16






153494_E_U_C.JPG: EASYSCAN SENSOR, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494

 page 12 of 16





153494_E_U_G.JPG: EASYSCAN SENSOR, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494

 page 13 of 16






153494_E_U_I.JPG: EASYSCAN SENSOR, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494
 page 14 of 16





153494_E_U_E.JPG: EASYSCAN SENSOR, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494

 page 15 of 16





153494_E_U_A.JPG: EASYSCAN SENSOR, test setup fully open area test site

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153494E3

 Date of issue:
 02/15/2016
 Order Number:
 15-113494
 page 16 of 16