



170032_4.JPG: EASYSCAN Link, internal view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F170032E1

 Date of issue:
 05/08/2017
 Order No.:
 17-110032

17-110032 page 1 of 10





170032_5.JPG: EASYSCAN Link, PCB sandwich


Examiner: Thomas KÜHN Date of issue: 05/08/2017

Test Report No.: F170032E1 Order No.: F170032



page 3 of 10


Annex C Internal photos



170032_6.JPG: EASYSCAN Link, PCB sandwich, battery removed


Examiner: Thomas KÜHN Date of issue: 05/08/2017 Test Report No.: F170032E1 Order No.: 17-110032






170032_8.JPG: EASYSCAN Link, PCB overview





170032_9.JPG: EASYSCAN Link, PCB 1, top view





170032_10.JPG: EASYSCAN Link, PCB 1, bottom view

Examiner: Thomas KÜHN Date of issue: 05/08/2017

Test Report No.: F170032E1 Order No.: 17-110032





170032_12.JPG: EASYSCAN Link, PCB 2, top view



page 8 of 10

Annex C Internal photos




170032_13.JPG: EASYSCAN Link, PCB 2, top view, shielding removed

Examiner: Thomas KÜHN Date of issue: 05/08/2017

Test Report No.: F170032E1 Order No.: 17-110032






170032_11.JPG: EASYSCAN Link, PCB 2, bottom view



Internal photos Annex C



170032_14.JPG: EASYSCAN Link, isolating PCB

Examiner: Thomas KÜHN Date of issue: 05/08/2017

Test Report No.: F170032E1 Order No.: 17-110032