

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973






1 Photographs of Conducted Emissions Test Configuration

Mode 3



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A6 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973







SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973






2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A6

Report Version

: Rev. 01




FCC Test Report


Report No. : FR411403-07AN

For radiated emissions 30MHz~1GHz

Mode 3



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A5 of A6 : Rev. 01

Report Version




FCC Test Report


Report No. : FR411403-07AN

For radiated emissions above 1GHz

Mode 2



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A6

Report Version : Rev. 01