## **Appendix A. Test Photos**

Report No. : FR411403-07AC

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01


CC Test Report Report No.: FR411403-07AC

## 1 Photographs of Conducted Emissions Test Configuration

Mode 3



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



Report No. : FR411403-07AC




**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01


CC Test Report No.: FR411403-07AC

## 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A4 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




CC Test Report No.: FR411403-07AC

For radiated emissions 30MHz~1GHz

Mode 3



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6
Report Version : Rev. 01



C Test Report No.: FR411403-07AC

For radiated emissions above 1GHz

Mode 2



**FRONT VIEW** 



: A6 of A6

: Rev. 01

**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version