

Report No.: FR411403-07AI

# **Appendix A. Test Photos**

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01






Report No. : FR411403-07AI

## 1 Photographs of Conducted Emissions Test Configuration

Mode 3



#### **FRONT VIEW**



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A6 TEL: 886-3-327-3456 Report Version : Rev. 01





Report No. : FR411403-07AI



**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01







Report No. : FR411403-07AI

### 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A4 of A6 TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report


Report No. : FR411403-07AI

For radiated emissions 30MHz~1GHz

Mode 3



### **FRONT VIEW**



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A5 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



### FCC Test Report


Report No. : FR411403-07AI

: A6 of A6

: Rev. 01

For radiated emissions above 1GHz

Mode 2



### **FRONT VIEW**



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version