




Report No.: FR632202AC

Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01





Report No. : FR632202AC



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01







Report No.: FR632202AC

1 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report

Report No.: FR632202AC

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5 : Rev. 01


Report Version



FCC Test Report

Report No.: FR632202AC

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A5 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01