Test report No.
 : 11211969H

 Page
 : 35 of 37

 Issued date
 : May 19, 2016

 FCC ID
 : ZVI-UDBP-RF8

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 11211969H

 Page
 : 36 of 37

 Issued date
 : May 19, 2016

 FCC ID
 : ZVI-UDBP-RF8

Radiated Spurious Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 11211969H

 Page
 : 37 of 37

 Issued date
 : May 19, 2016

 FCC ID
 : ZVI-UDBP-RF8

Worst Case Position

Above 1GHz (Horizontal: X-axis / Vertical: Z-axis) Below 1GHz (Horizontal: X-axis / Vertical: X-axis)






Y-axis



Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124