

Appendix A. Test Photos

Report No. : FR401709


SPORTON INTERNATIONAL INC. Page No. : A1 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01



1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01





SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01




2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW




REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A4 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01



For radiated emissions 30MHz~1GHz



FRONT VIEW



: A5 of A8


: Rev. 01

REAR VIEW


SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version



For radiated emissions 3GHz to 5GHz



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01



For radiated emissions above 1 GHz to 18 GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A7 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No. : FR4O1709



EUT took a close view



EUT took a close view

SPORTON INTERNATIONAL INC. Page No. : A8 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01