

# **Appendix A. Test Photos**

Report No.: FR4O1804

SPORTON INTERNATIONAL INC. Page No. : A1 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01





## 1 Photographs of Conducted Emissions Test Configuration



Report No.: FR4O1804

**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A8
Report Version : Rev. 01






**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01



### 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A4 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01



#### For radiated emissions 30MHz~1GHz



#### **FRONT VIEW**




### **REAR VIEW**

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A8
Report Version : Rev. 01



For radiated emissions 3GHz to 5GHz



**FRONT VIEW** 




**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A6 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01



For radiated emissions above 1 GHz to 18 GHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A7 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No. : FR4O1804

: A8 of A8

: Rev. 01



EUT took a close view



EUT took a close view

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version