




113239eut5.JPG: Controller-PCB

 Test engineer:
 Raimund BLASK
 Report Number:
 F113239E1

 Date of issue:
 19 December 2011
 Order Number:
 11-113239
 page 1 of 9






113239eut6.JPG: RF-PCB, front view

 Test engineer:
 Raimund BLASK
 Report Number:
 F113239E1

 Date of issue:
 19 December 2011
 Order Number:
 11-113239
 page 2 of 9






113239eut7.JPG: RF-PCB, rear view

 Test engineer:
 Raimund BLASK
 Report Number:
 F113239E1

 Date of issue:
 19 December 2011
 Order Number:
 11-113239
 page 3 of 9






113239eut8.JPG: Prozessor-Unit

 Test engineer:
 Raimund BLASK
 Report Number:
 F113239E1

 Date of issue:
 19 December 2011
 Order Number:
 11-113239
 page 4 of 9





113239eut9.JPG: Controller-Unit, front view

 Test engineer:
 Raimund BLASK
 Report Number:
 F113239E1

 Date of issue:
 19 December 2011
 Order Number:
 11-113239






113239eut10.JPG: Controller-Unit, rear view

 Test engineer:
 Raimund BLASK
 Report Number:
 F113239E1

 Date of issue:
 19 December 2011
 Order Number:
 11-113239
 page 6 of 9





113239eut13.JPG: DSP-Board

 Test engineer:
 Raimund BLASK
 Report Number:
 F113239E1

 Date of issue:
 19 December 2011
 Order Number:
 11-113239
 page 7 of 9






113239eut14.JPG: Synthesiser

 Test engineer:
 Raimund BLASK
 Report Number:
 F113239E1

 Date of issue:
 19 December 2011
 Order Number:
 11-113239
 page 8 of 9





113239eut15.JPG: Power Supply

 Test engineer:
 Raimund BLASK
 Report Number:
 F113239E1

 Date of issue:
 19 December 2011
 Order Number:
 11-113239
 page 9 of 9