


Appendix C. Setup Photographs

<Radiated Emission>

For 802.11a

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZW9AXCY1 Page Number : C1 of C4
Report Issued Date : Feb. 23, 2018
Report Version : Rev. 01

Report No.: FR792901-03D



Near View



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZW9AXCY1 Page Number : C2 of C4
Report Issued Date : Feb. 23, 2018
Report Version : Rev. 01

Report No.: FR792901-03D




For 802.11n HT20/HT40

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZW9AXCY1 Page Number : C3 of C4
Report Issued Date : Feb. 23, 2018
Report Version : Rev. 01

Report No.: FR792901-03D



Near View



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZW9AXCY1 Page Number : C4 of C4
Report Issued Date : Feb. 23, 2018
Report Version : Rev. 01

Report No. : FR792901-03D