SMART Response XE – CPU

Smart Response XE Terminal Reverse Engineering
This schematic is probably not 100% accurate. Some decoupling capacitors are missing.
Schéma du terminal Smart Response XE
Le schéma n'est probablement pas exacte à 100%. Condensateurs de découplage absents

Sheet: /
File: Smart_Response_XE.sch

Title: SMART Response XE – CPU

Size: A4   Date: 2021-09-08
KiCad E.D.A. kicad 5.1.12-84ad8e8a8692ubuntu20.04.1
Rev: 1.0
Id: 1/3

Components which value is ending with a * are not mounted
Les composants dont la valeur se termine par une * sont non montés

Sheet: Peripherals
File: peripherals.sch
DEBUG, SCK, MOSI, MISO, MEM_CS, MEM_HOLD, RX, TX, BUZZER, SCL, SDA, U5_INT
SCK2, MOSI2, MISO2

Sheet: keyboard
File: keyboard.sch
COL1, COL2, COL3, COL4, COL5, COL6
ROW1, ROW2, ROW3, ROW4, ROW5, ROW6, ROW7, ROW8, ROW9, ROW10
GND

U3 ATmega128RFA1
U4 TPS62203DBV
U1 uPG2214TB
B1 2450FB15L0001
L3 INDUCTOR
Y1 16MHz
Y2 32kHz
Z1
J1 JTAG
J2 ISP
P3 DISPLAY
BT1 4x1.5V

ANT1 Antenna
ANT2 Antenna

+3.3V +BATT PWR_FLAG GND

Enter key is routed but has no dome so there is no physical enter key
La touche enter est routée mais le dome est absent donc il n'y a pas de touche enter physique

+3.3V

| | | | | | | | | | | |
COL1

R27 47k

| SW2 | SW8 | SW14 | SW20 | SW26 | SW32 | SW38 | SW44 | SW50 | SW56 |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 0 |

COL2

R26 47k

| SW3 | SW9 | SW15 | SW21 | SW27 | SW33 | SW39 | SW45 | SW51 | SW57 |
| Q | W | E | R | T | Y | U | I | O | P |

COL3

R25 47k

| SW4 | SW10 | SW16 | SW22 | SW28 | SW34 | SW40 | SW46 | SW52 | SW58 |
| A | S | D | F | G | H | J | K | L | Bksp |

COL4

R24 47k

| SW5 | SW11 | SW17 | SW23 | SW29 | SW35 | SW41 | SW47 | SW53 | SW59 |
| Shft | Z | X | C | V | B | N | Down | Entr | Up |

COL5

R23 47k

| SW6 | SW12 | SW18 | SW24 | SW30 | SW36 | SW42 | SW48 | SW54 | SW60 |
| Sym | Frac | Root | Exp | Spc | , | . | M | Left | Right |

COL6

R22 47k

| SW7 | SW13 | SW19 | SW25 | SW31 | SW37 | SW43 | SW49 | SW55 | SW61 |
| SK1 | SK2 | SK3 | SK4 | SK5 | SK6 | SK7 | SK8 | SK9 | SK10 |

GNDD

ROW1 ROW2 ROW3 ROW4 ROW5 ROW6 ROW7 ROW8 ROW9 ROW10

Z4
D_Zener_x2_ACom_KAK
COL6 1 3 COL1
2

Z2
D_Zener_x2_ACom_KAK
COL4 1 3 COL5
2

Z5
D_Zener_x2_ACom_KAK*
COL4 1 3 COL5
2

Z7
D_Zener_x2_ACom_KAK*
1 3 COL1
2

Z3
D_Zener_x2_ACom_KAK
COL2 1 3 COL3
2

Z6
D_Zener_x2_ACom_KAK*
COL2 1 3 COL3
2

Z8
D_Zener_x2_ACom_KAK*
COL6 1 3
2

Smart Response XE Terminal Reverse Engineering
This schematic is probably not 100% accurate. Decoupling capacitors are missing.
Schéma du terminal Smart Response XE
Le schéma n'est probablement pas exact à 100%. Condensateurs de découplage absents

Sheet: /keyboard/
File: keyboard.sch

Title: SMART Response XE — Keyboard

Size: A4 | Date: 2021-09-09 | Rev: 1.0
KiCad E.D.A. kicad 5.1.12-84ad8e8a8692ubuntu20.04.1 | Id: 2/3

+3.3V

C30
C

U6
MAX3226*

C33
C*

2   C1+   C2+   5
4   C1−   C2−   6
              V+   3
              V−   7

C42
C*

C41
C*

C43

15 VCC

C*

+3.3V

C3
C

GND

+3.3V

R35
R*

TXD
R28
1 2
11 T1IN   T1OUT 13

RXD
R21
1 2
9   R1OUT   R1IN   8

J3
RS232
2 1
4 3
6 5

+3.3V
R*
12 FORCEON
16 FORCEOFF   READY   1
               INVALID 10

R37   LOGIC   GND   RS232

14

R36
R*

+BATT

R*
R10

BUZZERD

R9
R*

SP1
Buzzer*
1 2

Q1
NMOS ??

R39
R*

C18
C

D1
D*

BEWARE : On the PCB, drain and source of Q1 are swapped

+3.3V

U5
Mystery comp
1 10
2   9
3   8
4   7
5   6

+3.3V

C19
C

+3.3V

GND

C55
C

C25
C

U5_INTD

+3.3V
R13   R*

+3.3V

GND

R7
4.7k

R6
4.7k*

SCL
SDA

SCL
SDA

Despite missing R6, SDA is still pulled to
+3.3V through R41 (COL1) by about 30k Ohm.

+3.3V

U2
25LCxxx

R18
R*

R17
10k

MEM_HOLDD
3 WP   VCC 8
7 HOLD   SCK   6
1 CS   GND MOSI 5
              MISO 2

MEM_CSD

R3
33

R16
10k

CS_Flash

SCK
MOSI
MISO

+3.3V

R*
R14

LED*
D2

R*
R34

DEBUGD
1

Q2
PZT2222A*
3

C15 +3.3V
C

Sheet: /Peripherals/
File: peripherals.sch

Title: SMART Response XE — Peripherals

Size: A4   Date: 2021-09-09   Rev:
KiCad E.D.A. kicad 5.1.12-84ad8e8a8692ubuntu20.04.1   Id: 3/3