UF_PROCESS_AID_relation_type_e (view source)

Defined in: uf_process_aid_types.h

Also known as:

- UF_PROCESS_AID_relation_type_t
- UF_PROCESS_AID_relation_type_p_t

Overview

Datum object types

Data Members

```
UF_PROCESS_AID_RELATION_NONE_TYPE = 0
```

UF_PROCESS_AID_RELATION_FLUSH_TYPE

UF_PROCESS_AID_RELATION_GAP_TYPE

UF_PROCESS_AID_RELATION_NON_SPECIFIC_TYPE

UF_PROCESS_AID_types_e (view source)

Defined in: uf_process_aid_types.h

Also known as:

- UF_PROCESS_AID_types_t
- UF PROCESS AID types p t

Overview

Datum object types

Data Members

```
UF_PROCESS_AID_DATUM_LOC_SURF_TYPE = 1
```

UF_PROCESS_AID_DATUM_LOC_HOLE_TYPE = 1<<1

UF_PROCESS_AID_DATUM_LOC_SLOT_TYPE = 1<<2

UF_PROCESS_AID_DATUM_LOC_PIN_TYPE = 1<<3

UF_PROCESS_AID_DATUM_LOC_SURF_NA_TYPE = 1<<4

UF_PROCESS_AID_DATUM_LOC_HOLE_NA_TYPE = 1<<5

UF_PROCESS_AID_DATUM_LOC_SLOT_NA_TYPE = 1<<6 UF_PROCESS_AID_DATUM_LOC_PIN_NA_TYPE = 1<<7</pre> UF PROCESS AID DATUM PT TYPE = 1<<8 UF_PROCESS_AID_CERT_PT_TYPE = 1<<9 UF_PROCESS_AID_CERT_PT_NA_TYPE = 1<<10 UF_PROCESS_AID_MEA_SURF_VEC_TYPE = 1<<11 UF PROCESS AID MEA HOLE VEC TYPE = 1<<12 UF_PROCESS_AID_MEA_SLOT_VEC_TYPE = 1<<13 UF_PROCESS_AID_MEA_STUD_VEC_TYPE = 1<<14 UF_PROCESS_AID_MEA_TRIM_VEC_TYPE = 1<<15 UF_PROCESS_AID_MEA_HEM_VEC_TYPE = 1<<16 UF PROCESS AID MEA VEC NA TYPE = 1<<17 UF_PROCESS_AID_MEA_LOC_SURF_TYPE = 1<<18 UF_PROCESS_AID_MEA_LOC_HOLE_TYPE = 1<<19 UF_PROCESS_AID_MEA_LOC_SLOT_TYPE = 1<<20 UF_PROCESS_AID_MEA_LOC_PIN_TYPE = 1<<21 UF_PROCESS_AID_MEA_LOC_SURF_NA_TYPE = 1<<22 UF_PROCESS_AID_MEA_LOC_HOLE_NA_TYPE = 1<<23 UF_PROCESS_AID_MEA_LOC_SLOT_NA_TYPE = 1<<24 UF_PROCESS_AID_MEA_LOC_PIN_NA_TYPE = 1<<25 UF_PROCESS_AID_MEA_PT_TYPE = 1<<26

UF_PROCESS_AID_ALL_DATUM_TYPES = (1<<27)-1

All the types

UF_PROCESS_AID_WELD_types_e (view source)

Defined in: uf_process_aid_types.h

Also known as:

- UF_PROCESS_AID_WELD_types_t
- UF_PROCESS_AID_WELD_types_p_t

Overview

Weld types applicable for distance checks

Data Members

```
UF_PROCESS_AID_WELD_ARC_SPOT_TYPE = 1

UF_PROCESS_AID_WELD_SPOT_TYPE = 1<<1

UF_PROCESS_AID_WELD_CLINCH_TYPE = 1<<2

UF_PROCESS_AID_WELD_ARC_SPOT_NA_TYPE = 1<<3

UF_PROCESS_AID_WELD_SPOT_NA_TYPE = 1<<4

UF_PROCESS_AID_WELD_CLINCH_NA_TYPE = 1<<5
```

UF_PROCESS_AID_ALL_WELD_TYPES = (1<<6)-1