

(2) 白点 = -

(3) 形成气孔 = -

(4) 产生冷裂纹 = -

4. 控制氢的措施 =

(1) 限制焊接材料中的含氢量 = -