

Loading Arduino with USB

1 Connect Arduino to Computer

If your computer needs drivers direct it to the folder named "drivers"




2 open Xloader.exe in the Xloader folder



3 select the button next to hex file and select the program to load







5. Select the COM port <u>your</u> device is on (COM7 in the example. Yours may be different)



6. Click upload



7. Wait until you see the message ## bytes uploaded



8. Upload has been completed successfully.