System Efficiency between L258-2 (26137) and TYSONS (26165) for period 2019-08-16 00:00 to 2019-09-17 00:00

| System Efficiency (%): | -272.8 |
|------------------------|--------|
|------------------------|--------|

| Diverted (ML): | 414.5 | | |
|------------------------|---------------------|--|--|
| Delivered (ML): | 8.9 | | |
| Evaporative loss (ML): | 1.8 | | |
| Rainfall (ML): | 0.2 | | |
| Seepage loss (ML): | not yet implemented | | |
| Unaccounted loss (ML): | -13.7 | | |

Outlets

| Telemetered: | 1 |
|------------------|---|
| Manually read: | 2 |
| Unmetered sites: | 0 |
| Total: | 3 |

2 manually read meters are missing up to date readings.

| outlet | object_id | RTU_totaliser (ML) | flow_integral (ML) | manual_reading (ML) | diff | FG_calc |
|----------|-----------|--------------------|--------------------|---------------------|--------|---------|
| M2367A/1 | 64120 | | | | | |
| L258-3 | 26585 | 8.677 | 8.806 | | -1.469 | 8.860 |
| M2367A/3 | 67663 | | | | | |
| | Total | 0.0 | 0.0 | 0.0 | | 8.9 |

time of data collection: 2020-04-23 14:27

meters not read: 64120 67663